

1 Purpose

This document describes new functions, the changes, improvements and fixed bugs in the following firmware version:

- 57.1007.0018 for OS version 008

In comparison with the firmware version:

- 57.1007.0017 for OS version 007

2 New functions

The following new functions have been integrated:

- With **Direct DOS**, the filling rate/dosing rate can be changed (LQHRL-148).
- The TX-900MH impact printer is supported.
- Switching off the system is divided into "Shutting down the system" (standby) and "Switching off the system".

3 Improvements

The following improvements were made:

- None

4 Fixed bugs

The following bugs were fixed:

- Printing problems with PostScript printers (TITR-26352).
- System freezing at the end of the "Change cylinder unit" process.

5 Known issues

The following bugs are known:

- If an attempt is made to output the parameters as a PDF or via a Post-script printer directly after a factory reset, then the report will be empty.