

## 1 Purpose

This document describes the fixed bugs for the following new firmware versions:

- 5.848.0024
- 5.870.0024
- 5.877.0024
- 5.862.0024
- 5.865.0025
- 5.876.0025
- 5.885.0011
- 5.899.0011

## 2 Fixed bugs and problems

- The error "unrecoverable error" could occur if the instrument was switched on while a dosing device was connected.
- The error "unrecoverable error" occurred in continuous operation (e.g. during conditioning with the 899 Coulometer).

**Herisau, January 10, 2013**

---



P. Hunziker  
Vice President,  
Head of Development



U. Kürsteiner  
Head of Quality Management