

1 Purpose

This documents describes fixed bugs and problems for the new software version **856 Conductivity Module 5.856.0020**.

2 Fixed bugs and problems

- The bug *outlier in measurements* during the internal change-over of the measuring range, which was observed as a peak in the curve, is removed.
- The drift value was not applied correctly. With this correction, the measuring time can slightly change during drift-controlled measurements.

Herisau, 3 June, 2010



D. Strohm

Vice President, Head of R&D