
Release Notes

EN

1 Purpose

This document describes fixed bugs and problems in the following new firmware version:

- 5.884.0013

in comparison with the previous versions:

- 5.884.9912

2 Fixed Bugs and Problems

- Baud rate for data buffer transfer (DB transfer) was changed to 300'000 instead of 400'000 in order to prevent data buffer offset.

3 Compliance

The current firmware versions do not contain any modifications that affect the conformity of the instruments regarding 21 CFR Part 11.