

Corrigendum

1 Manuals

8.850.8015xx, 8.850.8016xx, 8.850.8017xx, 8.850.8024xx, 8.850.8025xx, 8.850.8026xx,
8.850.8027xx, 8.850.8028xx, 8.850.8045xx, 8.850.8046xx, 8.850.8047xx, 8.850.8048xx,
8.850.8049xx, 8.850.8050xx, 8.850.8051xx, 8.850.8052xx, 8.850.8053xx, 8.850.8054xx,
8.881.8009xx, 8.881.8010xx, 8.882.8009xx, 8.882.8010xx, 8.883.8001xx

2 Corrigendum

- DE: Beschriftung der Anschlusskapillaren MSM / MSM-HC / SPM geändert (siehe Abbildung unten).
- EN: Labels of MSM / MSM-HC / SPM connection capillaries changed (see figure below).
- CN: MSM / MSM HC / SPM 连接毛细管的标签已经更改（见下图）。
- ES: Se han cambiado las indicaciones de los capilares de conexión del MSM / MSM-HC / SPM (véase figura abajo).
- FR: Les inscriptions des capillaires de connexion sur le MSM / MSM-HC / SPM ont été modifiées (voir figure ci-dessous).
- KR: MSM / MSM HC / SPM 연결 모세관의 명칭이 변경됨(아래 그림 참조).
- PT: Marcação dos capilares de conexão MSM / MSM HC / SPM alterada (ver figura abaixo).
- JP: MSM / MSM HC / SPMの接続キャピラリーの標記が変更されました（下図参照）。

