

## 1 Purpose

This document describes the changes, improvements and fixed bugs in the following firmware version:

- 5.885.0031

In comparison with the firmware version:

- 5.885.0030

## 2 New functions

None

## 3 Improvements

- The rack is initialized when a sample series is started. The **number of samples** and the **Next sample pos.** can be entered at the same time. The processing of the samples can be started as soon as the rack is initialized.
- In the method run, the sample beaker and the conditioning beaker are approached on the rack with the shortest path.

## 4 Fixed bugs

- Printers of the type Epson (ESC-POS) were not recognized.