

1 Devices

The firmware version below can be used with the following instruments:

- 947 Professional UV/VIS Detector Vario SW (2.947.0010)
- 947 Professional UV/VIS Detector Vario MW (2.947.0020)

2 Purpose

This document describes the new features, the improvements and the fixed bugs in the following new firmware version:

- 5.947.0210

In comparison with the firmware version:

- 5.947.0101

3 New features

Topic	Description
None	None

4 Improvements

Topic	Description
None	None

5 Fixed bugs

Topic	Description
Defective UV lamp	The instrument did not generate an error code when defective UV lamps failed to ignite.
VIS lamp optimization	The optimization of the VIS lamp did not function correctly in rare cases.

6 Known issues

Topic	Description
None	None