

## 1 Purpose

This document describes the fixed bugs in the following firmware version:

- 5.947.0221

In comparison with the firmware version:

- 5.947.0210

## 2 Fixed bugs

The following bugs were fixed:

- Fixed real-time increment in operating hour counter of both lamps.
- Fixed VIS lamp optimization progress that could get stuck under certain intensity conditions.