

## 1 Purpose

This document describes new functions, the changes, improvements and fixed bugs and problems in the following firmware version:

- 57.1007.0013 for OS version 005

in comparison with the firmware version:

- 57.1007.0012 for OS version 005

## 2 New functions

The following new functions have been integrated:

- None

## 3 Improvements

The following improvements were made:

- Special characters are now allowed in method names. Still not allowed are: ( % ! / :\* ? < . > " )

## 4 Fixed bugs and problems

The following bugs and problems were fixed:

- During direct dosing (Direct DOS), the screen sometimes froze (SERV-17426). If the piston reached the upper or lower end and a user interaction took place at the same time, then the instrument could remain stuck.

## 5 Known bugs and problems

The following bugs or problems are known:

- If, after a factory reset, the user tries to print parameters directly on a PDF or Postscript printer, the parameter report is empty.