

1 Purpose

This document describes new functions, the changes, improvements and fixed bugs in the following firmware version:

- 57.1007.0014 for OS version 006

in comparison with the firmware version:

- 57.1007.0013 for OS version 005

2 New functions

The following new functions have been integrated:

- None

3 Improvements

The following improvements were made:

- Optimizations for the overall instrument test in the production.

4 Fixed bugs

The following bugs were fixed:

- Problem with the DHCP IP address in the production.

5 Known bugs

The following bugs are known:

- If, after a factory reset, the user tries to print parameters directly on a PDF or Postscript printer, the parameter report is empty.