

1 Purpose

This document describes new functions, changes, and improvements in the following firmware version:

- 57.1008.0020 for OS version 008

In comparison with the firmware version:

- 57.1008.0018 for OS version 007

2 New functions

The following new functions have been integrated:

- Exchange function for PT1000 temperature coefficients added in the service menu (NCM-8722).

3 Improvements

The following improvements were made:

- Polarizer test improvements for production and service.
- Optimizations for tests in production (OS version 008).

4 Fixed bugs

The following bugs were fixed:

- Polarizer test fails. (SERV-19642, SERV-19891, SERV-21064, SERV-24219, SERV-24720).

5 Known issues

The following bugs are known:

- None