

1 Purpose

This document describes the differences between the new software version **viva 2.0 Patch 1 (Build 54-1)** and its predecessor **viva 2.0 (Build 54)**.

2 Fixed bugs and problems

New instrument firmware

New firmware version for the instruments 884 Professional VA and 894 Professional CVS: 5.884.0013.

The new firmware reduces stability issues that can occur during voltammetric measurements.

3 Signatures

Herisau, June 30, 2017



P. Hunziker
Vice President,
Head of Development



Dr. M. Saba
Head of Quality Management