

1 Instruments

The firmware version below can be used with the following instruments:

- 850 Professional IC
- 881 Compact IC pro
- 882 Compact IC plus
- 883 Basic IC plus
- 920 Absorber Module
- 925 Eco IC

2 Purpose

This document describes the new features, the improvements as well as the fixed bugs and problems in the following new firmware versions:

- 5.850.0113

In comparison with the firmware versions:

- 5.850.0112

3 New features

| Topic | Description |
|-------|-------------|
| none | none |

4 Improvements

| Topic | Description |
|-------|-------------|
| none | none |

5 Fixed bugs and problems

| Topic | Description |
|----------------|---|
| System stopped | In certain cases, the IC system was stopped by mistake due to the error situation "Minimum pressure fallen below", even though the system pressure remained stable. |


6 Known bugs

| Topic | Description |
|-------|-------------|
| none | none |

7 Conformity

The firmware version 5.850.0113 does not contain any modifications that affect conformity of the instruments mentioned above regarding 21 CFR Part 11 and GAMP.

Herisau, June 22, 2018



P. Hunziker
Vice President,
Head of Development



M. Saba
Head of Quality Management & Reg-
ulatory Affairs