

1 Purpose

This document describes the fixed bugs and problems for the new firmware versions 5.865.0023 and 5.876.0023.

2 Improvements

- The PC/LIMS report (not compatible to TiBase) has been integrated for Dosimats.

3 Fixed bugs and problems

- An error message appeared if during a filling process which had been started via the remote interface a second filling impulse was sent. This message could only be confirmed manually on the instrument. Now, a filling impulse during a filling process is ignored.

4 Compliance

The current software version does not contain any modifications regarding 21 CFR Part 11.

Herisau, 3 May, 2011



Dr. J. Kleimann
Vice President, Head of R&D



U. Kürsteiner
Head of Quality Management