

884 Professional VA / 894 Professional CVS

FPGA Version: 124

Release Notes

8.884.3005EN / 2018-02-09



Metrohm AG
Ionenstrasse
CH-9100 Herisau
Switzerland
Phone +41 71 353 85 85
Fax +41 71 353 89 01
info@metrohm.com
www.metrohm.com

884 Professional VA / 894 Professional CVS

Release Notes

8.884.3005EN /
2018-02-09

Technical Communication
Metrohm AG
CH-9100 Herisau
techcom@metrohm.com

This documentation is protected by copyright. All rights reserved.

This documentation has been prepared with great care. However, errors can never be entirely ruled out. Please send comments regarding possible errors to the address above.

1 Purpose

This document describes fixed bugs and problems in the following new FPGA version:

- 124

in comparison with the previous versions:

- 122
- 114



2 Fixed Bugs and Problems

- The new FPGA version fixes problems that occurred during measurements with the instruments 884 Professional VA and 894 Professional CVS. The problems are caused by incorrect error handling in the data recording procedures under critical timing conditions. The problems resulted in error messages in viva.



3 Compliance

The current FPGA versions do not contain any modifications that affect the conformity of the instruments regarding 21 CFR Part 11.