

1 Purpose

This document describes the improvements as well as the known bugs in the following new firmware versions:

- 5.900.0031-1
- 5.915.0031-1
- 5.916.0031-1


in comparison with the firmware versions:

- 5.900.0031
- 5.915.0031
- 5.916.0031

2 Improvements

| Topic | Description |
|-----------------|--|
| Reduced crashes | The occurrence of crashes was further reduced. |

3 Known bugs

| Topic | Description |
|---|---|
| IQ/OQ | The message box does not appear anymore in the dialog for the test step 7.51. |
| Fixed key  | Screenshots can be printed only on the connected printer. When creating screenshots as a PDF, the PDF file is generated but has no contents. |
| HP Office Jet 8000 | The curve printout on HP Office Jet 8000 does not work. |

4 Compliance

The current firmware version 5.900.0031-1 does not contain any modifications that affect the conformity of the 900 Touch Control regarding 21 CFR Part 11

and GAMP. The firmware versions 5.915.0031-1 and 5.916.0031-1 contain no compliance regarding 21 CFR Part 11 and GAMP.

Herisau, July 9, 2015



P. Hunziker
Vice President,
Head of Development



M. Matter
Head of Quality Management