

1 Purpose

This document describes the new features, the improvements as well as the fixed bugs and problems in the following new firmware versions:

- 5.912.0014
- 5.913.0014
- 5.914.1014
- 5.914.2014

In comparison with the firmware versions:

- 5.912.0013
- 5.913.0013
- 5.914.1013
- 5.914.2013

2 New features

Topic	Description
Impact printer available	Epson TM-U220B (2.143.0100) impact printer was added to printer selection

3 Improvements

Topic	Description
none	none

4 Fixed bugs and problems

Topic	Description
Wrong measured value in measured value list	Wrong measured values were output after 25 days of continuous measurement.

Topic	Description
Wrong error message for limit values when using iTrodes	With limit value monitoring activated when calibrating an iTrode with a 913 pH Meter, limit values were marked as violated even if they were not.

5 Known bugs

Topic	Description
none	none

Herisau, June 13, 2018



P. Hunziker
Vice President,
Head of Development



M. Saba
Head of Quality Management &
Regulatory Affairs