





## Accessories for 6.5616.100

Below, the accessories are grouped into Scope of delivery and Optional accessories.  
Please keep this printout at hand for ordering replacement material.  
These lists may be subject to change.

### Scope of delivery 6.5616.100

Qty.	Order no.	Description	
1 pcs	6.1111.010	<b>Pt100 temperature sensor for stability measuring devices</b>	
		Pt100 temperature sensor (length 17.5 cm) with fixed cable and mini-DIN-plug. This glass-free temperature sensor is well suited for use with a 711 Liquino and instruments for stability measurement (743 Rancimat, 763 PVC Thermomat, 892 Professional Rancimat, or 895 Professional PVC Thermomat).	
2 pcs	6.2042.040	<b>Clamp for temperature sensor</b>	
		Holding clamp for Pt100 temperature sensor for stability measuring instruments	
1 pcs	6.2326.000	<b>Silicone oil for stability measuring instruments (50 mL)</b>	
		Silicone oil for the determination of temperature correction in stability measuring instruments	
1 pcs	6.2418.000	<b>Air tube for oil measurements</b>	
		Set of 12 pieces. In combination with 6.1429.040.	