

Additional accessory

The following items are required in addition to run the system:

MVA	1	2	3	11	12	13
Windows™ PC	x	x	x	x	x	x
Nitrogen	x	x	x	–	–	–
Pressure regulator	x	x	x	–	–	–
Mercury	x	x	x	–	–	–
Ultrapure water	x	x	x	x	x	x

x = required accessory

