

828 IC Dual Suppressor

8.828.1011 Annex to the 8.828.1001 Instructions for use

Shutdown

section 5.3

If the device is shut down for more than one week, the suppressor rinsing described in the stop sequence (*section 3.6.1/3.6.2*) should last 1.5 hours (not only 15 minutes, as described before).