

## 1 Purpose

This document describes the differences between the new software version **Metrohm IC Driver for Empower™ 1.1** and its predecessor **Metrohm IC Driver for Empower™ 1.0**.

This release of **Metrohm IC Driver for Empower™ 1.1** replaces all previous releases.

## 2 Improvements

1. Integration of device family **930 Compact IC Flex**.  
(version: 2.930.1100, 2.930.1160, 2.930.1200, 2.930.1260, 2.930.1300, 2.930.1360, 2.930.1400, 2.930.1460, 2.930.1500, 2.930.1560, 2.930.2100, 2.930.2160, 2.930.2200, 2.930.2260, 2.930.2300, 2.930.2360, 2.930.2400, 2.930.2460, 2.930.2500, 2.930.2560)
2. Integration of device family **940 Professional IC Vario**.  
(version: 2.940.1100, 2.940.1110, 2.940.1200, 2.940.1300, 2.940.1400, 2.940.1410, 2.940.1500)

## 3 Fixed bugs and problems

none

## 4 Known problems for resolution in next release

none

Herisau, December 16, 2013



**Herisau, December 16, 2013**

---

P. Hunziker  
Vice President,  
Head of Development

U. Kürsteiner  
Head of Quality Management