

## 1 Purpose

This document describes the fixed bugs and problems for the new firmware versions 5.848.0022, 5.862.0022, 5.865.0022, 5.869.0022, 5.870.0022, 5.876.0022, 5.877.0022.

## 2 Fixed bugs and problems

- The keyboard supplied with the titrators and Dosimats does not work properly anymore because its hardware has been modified.
- 862, manual control, dosing: the system freezes if Portuguese is selected as language and dosing is started.
- 862, system settings: the setting **PC/LIMS report = COM2** is reset to **USB Stick** when switching on the instrument.
- 862: in the method parameters, the result units **-70** und **-71** exist.

## 3 Compliance

The current software version does not contain any modifications regarding 21 CFR Part 11.

**Herisau, 12 November, 2010**

---



D. Strohm

Vice President, Head of R&D